



## Cable Assembly Instruction: TNC-01

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Clamp


STEP 1. All parts of the connector are under shown.




STEP 2. Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" shown above.




STEP 3. Insert inner conductor into the CONTACT PIN, and solder it as under shown. Then slide the HEX NUT, WASHER, and GASKET on to cable one by one.



STEP 4. Place the TOP HAT over braid and push back against cable jacket. Fold back braid wire as under shown.




STEP 5. Insert cable and parts into the MAIN BODY, then screw the HEX NUT until it is tighten.




## Cable Assembly Instruction: FME-05

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Crimp


**STEP 1.** All parts of the connector are under shown. A crimp tool is necessary to complete the connection.




**STEP 2.** Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" as above shown.




**STEP 3.** Insert inner conductor into the CONTACT PIN, crimp it with the crimp tool as under shown. Then slide the FERRULE on to cable.



**STEP 4.** Insert the main BODY into braid and dielectric.




**STEP 5.** Slide the FERRULE over braid, crimp it with the crimp tool as under shown.




## Cable Assembly Instruction: FME-06

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Crimp


**STEP 1.** All parts of the connector are under shown. A crimp tool is necessary to complete the connection.




**STEP 2.** Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" as above shown.




**STEP 3.** Insert inner conductor into the CONTACT PIN, crimp it with the crimp tool as under shown. Then slide the FERRULE on to cable.



**STEP 4.** Insert the main BODY into braid and dielectric.




**STEP 5.** Slide the FERRULE over braid, crimp it with the crimp tool as under shown.




## Cable Assembly Instruction: MU-03

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Crimp


**STEP 1.** All parts of the connector are under shown. A crimp tool is necessary to complete the connection.




**STEP 2.** Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" as above shown.




**STEP 3.** Insert inner conductor into the CONTACT PIN, crimp it with the crimp tool as under shown. Then slide the FERRULE on to cable.



**STEP 4.** Insert the main BODY into braid and dielectric.




**STEP 5.** Slide the FERRULE over braid, crimp it with the crimp tool as under shown.




## Cable Assembly Instruction: SMA-03

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Crimp


**STEP 1.** All parts of the connector are under shown. A crimp tool is necessary to complete the connection.




**STEP 2.** Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" as above shown.




**STEP 3.** Insert inner conductor into the CONTACT PIN, crimp it with the crimp tool as under shown. Then slide the FERRULE on to cable.



**STEP 4.** Insert the main BODY into braid and dielectric.




**STEP 5.** Slide the FERRULE over braid, crimp it with the crimp tool as under shown.




## Cable Assembly Instruction: SMA-04

### Recommended Cable Stripping Dimension




### Cable Assembly Instruction for Crimp


**STEP 1.** All parts of the connector are under shown. A crimp tool is necessary to complete the connection.




**STEP 2.** Strip the cable inner conductor, dielectric braid, and jacket as "RECOMMENDED CABLE STRIPPING DIM'S" as above shown.



**STEP 3.** Insert inner conductor into the CONTACT PIN, crimp it with the crimp tool as under shown. Then slide the FERRULE on to cable.



**STEP 4.** Insert the main BODY into braid and dielectric.



**STEP 5.** Slide the FERRULE over braid, crimp it with the crimp tool as under shown.

